

J .	)						
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Slauson-01	Cafeteria, Hydration Station Bottle Fill	BT	3:57 PM	5	ND <sup>3</sup>	N	First Draw.
Slauson-04			- 	OPEN NUM	BER		
Slauson-05	Girls Locker Room, Bubbler	В	3:40 PM	5	ND	N	First Draw, Corrosion.
Slauson-06	Boys Locker Room, Bubbler	В	3:42 PM	5	ND	N	First Draw, Corrosion.
Slauson-07	Hallway, Outside of Room 146, Water Cooler	WC	Not Sampled				Scheduled for replacement with a Hydrati Station.
Slauson-10	Room 138, 2-Comp, Kitchen Faucet	KF	3:46 PM	5	ND	Y	First Draw
Slauson-11	Hallway, Outside of Room 138, Bubbler	В		Not Sar	mpled	Scheduled for replacement with a Hydrati Station.	
Slauson-12	Men's Locker Room, Bubbler	В	3:53 PM	5	1	N	First Draw
Slauson-13	Pool Deck, Water Cooler	WC	3:50 PM	5	ND	N	First Draw
Slauson-14	Women's Locker Room, Water Cooler	WC		Not Sar	mpled	Out of Service.	
Slauson-15	Hallway, Outside Room 224, Bubbler	В	Not Sampled				Scheduled for replacement with a Hydrati Station.
Slauson-16	Hallway, Outside Room 204, Bubbler	В	Not Sampled				Scheduled for replacement with a Hydrati Station.
Slauson-17	Library Lounge, Kitchen Faucet	KF	3:13 PM	5	39	Y	First Draw. Corrosion.
Slauson-18	Hallway, Outside Library Lounge, Single Water Cooler	WC	3:16 PM	5	28	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

2) https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante 3) ND = Non Detected at Reported Detection Limit of 1 ug/L

4) NT = Not Tested



7	,								
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes		
Slauson-19	Hallway, Outside Library Lounge, Hydration Station Bottle Fill	ВТ	3:15 PM	5	ND	N	First Draw		
Slauson-20	Hallway, Outside Library Lounge, Hydration Station Water Cooler	ВТ	3:14 PM	5	ND	N	First Draw		
Slauson-21	Main Office Kitchen Faucet	KF	3:18 PM	5	6	N	First Draw. Corrosion.		
Slauson-22	Gym, Hydration Station Bottle Fill	ВТ	3:37 PM	5	ND	Ν	First Draw		
Slauson-23	Gym, Hydration Station Water Cooler	WC	3:36 PM	5	ND	N	First Draw		
Slauson-24	Auditorium Lobby, Hydration Station Bottle Fill	ВТ	3:21 PM	5	ND	N	First Draw		
Slauson-25	Auditorium Lobby, Hydration Station Water Cooler	вт	3:20 PM	5	ND	N	First Draw		
Slauson-26	Auditorium Lobby, Single Water Cooler	WC	3:22 PM	5	ND	N	First Draw		
Slauson-27	Hallway, Outside Room 203, Bubbler	В		Not Sar	npled	Scheduled for replacement with a Hydra Station.			
Slauson-28	Hallway, Outside Room 324, Bubbler	В		Not Sar	npled	Scheduled for replacement with a Hydra Station.			
Slauson-29	Room 346, Faucet	F		Not Sar	npled	Out of Service.			
Slauson-30	Hallway, Outside Room 348, Water Cooler	WC		Not Sar	npled	Scheduled for replacement with a Hydra Station.			
Slauson-31	Computer Room, Rooms 300 & 300A, Faucet	F	3:25 PM	5	6	Y	First Draw		
Slauson-33		OPEN NUMBER							

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

2) https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante 3) ND = Non Detected at Reported Detection Limit of 1 ug/L



5 5							
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Slauson-34	Hallway, Outside Room 303, Bubbler	В					Scheduled for replacement with a Hydration Station.
Slauson-37	Cafeteria, Hydration Station Water Cooler	BF	3:56 PM	5	ND	N	

 Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee
https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante
ND = Non Detected at Reported Detection Limit of 1 ug/L
NT = Not Tested



,	,						
Sample #	Location	Type <sup>1</sup>	Time Collected	Internal Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	Notes
Slauson-02	Hallway, Outside of Lower Gym, Hydration Station Bottle Fill	вт	9:20 AM	5	ND	N	First Draw
Slauson-03	Hallway, Outside of Lower Gym, Hydration Station Water Cooler	BT	9:21 AM	5	ND	N	First Draw
Slauson-08	Room 138, Special Education, Single Sink, Left Faucet	F	9:28 AM	5	ND	Y	First Draw
Slauson-09	Room 138, Special Education, Single Sink, Right Faucet	F	9:29 AM	5	ND	Y	First Draw
Slauson-32	Room 211, Faucet	F	9:38 AM	5	6	N	First Draw
Slauson-35	Kitchen, 3-Compartment, Right Faucet	KS	9:33 AM	5	ND	N	First Draw
Slauson-36	Kitchen, 3-Compartment, Left Faucet	KS	9:32 AM	5	ND	N	First Draw
Slauson-38	Room 203, Faucet	F	9:35 AM	5	7	Y	First Draw. Corrosion observed on Fauce
Slauson-39	Clinic, Faucet	F	9:40 AM	5	9	Y	First Draw
Slauson-40	Room 321, Work Room, Faucet	F	9:47 AM	5	36	N	First Draw
Slauson-41	Room 323, Work Room, Faucet	F	9:44 AM	5	89	Y	First Draw
Slauson-42	Lower Auxiliary Gym, Water Cooler	WC	9:24 AM	5	ND	N	First Draw

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

2) https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante 3) ND = Non Detected at Reported Detection Limit of 1 ug/L

4) NT = Not Tested